Lake View Cemetery Bu	3.2									
Lake View Cemetery Bu	5.3	Poor	G2012 Asphalt- overlay 1"	95000	SF	$1.14	$108,300			
Lake View Cemetery Bu	5.3	Fair to Poor	G2023A Replace stone curbs	40	LF	$31.95	$1,278	$ 1,278		
Lake View Cemetery Bu	5.4	Poor	G2042 Replace stone retaining wall, mortar set	250	SF Fa	$75.25	$18,813	$ 18,813		
Lake View Cemetery Bu	5.5	Poor	G2041 Replace wrought iron fence 3' high	1133	LF	$28.50	$32,291	$ 32,291		
Lake View Cemetery Bu	6.6	Fair	B2031A Prepare and refinish 3'-0" wide steel door	2	EA	$493.00	$986		$ 986	
Lake View Cemetery Bu	6.6	Fair	B2031A Prepare and refinish solid core, painted, door	3	EA	$361.00	$1,083	$ 1,083		
Lake View Cemetery Bu	6.7	Poor	B1012 Porch Roof Deck and Structure Replacement	160	SF	$75.00	$12,000	$ 12,000		
Lake View Cemetery Bu	6.7	Fair to Poor	C2011A Replace wood steps	25	SF	$103.10	$2,578		$ 2,578	
Lake View Cemetery Bu	7.1	Fair	D3051 Window air-conditioner 12,000 Btuh	1	Each	$761.99	$762		$ 762	
Lake View Cemetery Building										
										$ 69,791