

OF VERMONT  
 Division for Historic Preservation  
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY  
 Individual Structure Survey Form

SURVEY NUMBER:

NEGATIVE FILE NUMBER:

78-A-121

UTM REFERENCES:

Zone/Easting/Northing

U.S.G.S. QUAD. MAP:

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: apartments

ORIGINAL USE: residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent  Good

Fair  Poor

STYLE:

Greek Revival

DATE BUILT:

1850

COUNTY: Chittenden  
 TOWN: Burlington  
 LOCATION:  
 111 North Winooski  
 COMMON NAME:  
 FUNCTIONAL TYPE:  
 OWNER: George Munson  
 ADDRESS: 97 North Winooski  
 ACCESSIBILITY TO PUBLIC:  
 Yes  No  Restricted   
 LEVEL OF SIGNIFICANCE:  
 Local  State  National

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone  Brick  Concrete  Concrete Block
2. Wall Structure
  - a. Wood Frame: Post & Beam  Balloon
  - b. Load Bearing Masonry: Brick  Stone  Concrete   
Concrete Block
  - c. Iron  d. Steel  e. Other: *addition*
3. Wall Covering: Clapboard  Board & Batten  Wood Shingle   
Shiplap  Novelty  Asbestos Shingle  Sheet Metal   
Aluminum  Asphalt Shingle  Brick Veneer  Stone Veneer   
Bonding Pattern: Other: *brick*
4. Roof Structure
  - a. Truss: Wood  Iron  Steel  Concrete
  - b. Other:
5. Roof Covering: Slate  Wood Shingle  Asphalt Shingle   
Sheet Metal  Built Up  Rolled  Tile  Other:
6. Engineering Structure:
7. Other:

Appendages: Porches  Towers  Cupolas  Dormers  Chimneys   
Sheds  Ells  Wings  Bay Window  Other:

Roof Style: Gable  Hip  Shed  Flat  Mansard  Gambrel   
Jerkinhead  Saw Tooth  With Monitor  With Bellcast   
With Parapet  With False Front  Other:

Number of Stories: 2 1/2

Number of Bays:

Entrance Location:

Approximate Dimensions: 20 x 70

THREAT TO STRUCTURE:

No Threat  Zoning  Roads   
Development  Deterioration   
Alteration  Other:

LOCAL ATTITUDES:

Positive  Negative   
Mixed  Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Massing - Pedimented gable front orientation. 3 bays wide. Boxed cornice. Porch wraps around to south elevation. Canted bay window on south elevation. Clapboard ell.

Fenestration - 1/1 sash. Symetrical arrangement. Flat arches, blind semi-elliptical arch in gable.

Entrance - Right. Sidelights. Nor original-Queen Anne.

Enrichments - Turned posts on pedestals. Turned balusters, Bracketed cornice on porch. Rope molding around door.

RELATED STRUCTURES: (Describe)

Carriage house in rear - now a shop.


STATEMENT OF SIGNIFICANCE:

A common Greek Revival house type found in Burlington, characterized by a 3 bay facade with side hall entrance, pedimented gable and gable window. Although built before 1853, nothing is known of it until 1865, when it was the home of David Read, City Recorder. In both style and function, the building maintains the character of the neighborhood.

REFERENCES:

1853, 1869, 1890, Sanborns, directories.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

Open Land  Woodland   
Scattered Buildings   
Moderately Built Up   
Densely Built Up   
Residential  Commercial   
Agricultural  Industrial   
Roadside Strip Development   
Other:

RECORDED BY:

C. Richard Morsbach

ORGANIZATION:

VT. Div. for Historic Preservation

DATE RECORDED:

6/8/78