STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 112 Howard St.
NEGATIVE FILE NUMBER: 77-A-277
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: dwelling
ORIGINAL USE: dwelling
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent ■ Good ☐ Fair ☐ Poor ☐
THEME:
STYLE: Italianate
DATE BUILT: 1885

COUNTY:
TOWN:
LOCATION:
COMMON NAME:
FUNCTIONAL TYPE: dwelling
OWNER: Donald & Jennie Bushey
ADDRESS: 112 Howard
ACCESSIBILITY TO PUBLIC: Yes ☐ No ■ Restricted ☐
LEVEL OF SIGNIFICANCE: Local ■ State ■ National ☐

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone ☐ Brick ☐ Concrete ■ Concrete Block ☐
2. Wall Structure
   a. Wood Frame: Post & Beam ☐ Balloon ■
   b. Load Bearing Masonry: Brick ☐ Stone ☐ Concrete ☐ Concrete Block ☐
   c. Iron ☐ d. Steel ☐ e. Other:
3. Wall Covering: Clapboard ■ Board & Batten ☐ Wood Shingle ☐ Shiplap ☐ Novelty ☐ Stucco ☐ Sheet Metal ☐ Aluminum ☐ Asphalt Shingle ☐ Brick Veneer ☐ Stone Veneer ☐
   Bonding Pattern: Other:
4. Roof Structure
   a. Truss: Wood ☐ Iron ☐ Steel ☐ Concrete ☐
   b. Other:
5. Roof Covering: Slate ■ Wood Shingle ☐ Asphalt Shingle ☐ Sheet Metal ☐ Built Up ☐ Rolled ☐ Tile ☐ Other:
6. Engineering Structure:
7. Other:

Appendages: Porches ■ Towers ☐ Cupolas ☐ Dormers ☐ Chimneys ☐ Sheds ☐ Ells ☐ Wings ☐ Other:
Roof Style: Gable ■ Hip ☐ Shed ☐ Flat ☐ Mansard ☐ Gambrel ☐ Jerkinhead ☐ Saw Tooth ☐ With Monitor ☐ With Bellcast ☐ With Parapet ☐ With False Front ☐ Other:
Number of Stories: 1 1/2
Number of Bays: 2 x 2
Approximate Dimensions:
Entrance Location: right wall

THREAT TO STRUCTURE: No Threat ☐ Zoning ☐ Roads ☐ Development ☐ Deterioration ☐ Alteration ☐ Other:

LOCAL ATTITUDES: Positive ☐ Negative ☐ Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Small rectangular block with porch and entrance on east wall. Imbricated belt of slate across roof. Round headed 2/2 sash window in gable end. 2/2 sash windows on 1st story with sholdered moldings. Similar surround on door.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

REFERENCES:

MAP: (Indicate North In Circle)

SURROUNDING ENVIRONMENT:

- Open Land ☐ Woodland ☐
- Scattered Buildings ☐
- Moderately Built Up ☐
- Densely Built Up ■
- Residential ■ Commercial ☐
- Agricultural ☐ Industrial ☐
- Roadside Strip Development ☐
- Other:

RECORDED BY: Clark Schuttle

ORGANIZATION: VT Division for Historic Preservation

DATE RECORDED: 10/22/77