STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 0402

NEGATIVE FILE NUMBER: 83-A-91

UTM REFERENCES: Zone/Easting/Northing 18/638540/4929800

U.S.G.S. QUAD. MAP: Burlington 7.5

PRESENT FORMAL NAME: Lionel Smith House

ORIGINAL FORMAL NAME: Alfred Trombley House

PRESENT USE: House

ORIGINAL USE: House

ARCHITECT/ENGINEER: Unknown

BUILDER/CONTRACTOR: Unknown

PHYSICAL CONDITION OF STRUCTURE: Excellent ☐ Good ■ Fair ☐ Poor ☐

STYLE: Dutch Colonial Revival

DATE BUILT: 1926

COUNTY: Chittenden

TOWN: Burlington

LOCATION: 124 Staniford Road, North side of road. Approximately 1/4 mile west from corner of North Avenue.

COMMON NAME:

FUNCTIONAL TYPE: House

OWNER: Lionel & Theresa Smith

ADDRESS: 124 Staniford Road
Burlington, VT 05401

ACCESSIBILITY TO PUBLIC: Yes ☐ No ■ Restricted ☐

LEVEL OF SIGNIFICANCE: Local ☐ State ■ National ☐

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone ☐ Brick ☐ Concrete ☐ Concrete Block ■
2. Wall Structure
   a. Wood Frame: Post & Beam ☐ Balloon ■
   b. Load Bearing Masonry: Brick ☐ Stone ☐ Concrete ☐ Concrete Block ☐
   c. Iron ☐ d. Steel ☐ e. Other:
3. Wall Covering: Clapboard ☐ Board & Batten ☐ Wood Shingle ■ Shiplap ☐ Novelty ☐ Asbestos Shingle ☐ Sheet Metal ☐ Aluminum ☐ Asphalt Shingle ☐ Brick Veneer ☐ Stone Veneer ☐ Bonding Pattern: Other:
4. Roof Structure
   a. Truss: Wood ■ Iron ☐ Steel ☐ Concrete ☐
   b. Other:
5. Roof Covering: Slate ☐ Wood Shingle ☐ Asphalt Shingle ■ Sheet Metal ☐ Built Up ☐ Rolled ☐ Tile ☐ Other:
6. Engineering Structure:
7. Other:

Appendages: Porches ■ Towers ☐ Cupolas ☐ Dormers ☐ Chimneys ■ Sheds ☐ Ells ☐ Wings ☐ Bay Window ☐ Other:

Roof Style: Gable ☐ Hip ☐ Shed ☐ Flat ☐ Mansard ☐ Gambrel ■ Jerkinhead ☐ Saw Tooth ☐ With Monitor ☐ With Bellcast ☐ With Parapet ☐ With False Front ☐ Other:

Number of Stories: 2

Number of Bays: 3 x 3

Approximate Dimensions: 20 x 26

Entrance Location: Eaves front, center and right

THREAT TO STRUCTURE: No Threat ☐ Zoning ☐ Roads ☐ Development ☐ Deterioration ☐ Alteration ☐ Other:

LOCAL ATTITUDES: Positive ☐ Negative ☐ Mixed ☐ Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Two story rectangular plan house with spring eaves, exposed rafter ends and center shed dormer with four 2/1 sash windows and plain surrounds. Front porch under extended spring eaves roof with chamfered posts and aluminum sided. Rear two story wing attached at curb line (before 1947) and rear shed addition with enclosed entrance. Symmetrical facade interrupted by right side entrance to second story apartment. Paneled front doors. 2/2 sash windows with plain surrounds.

RELATED STRUCTURES: (Describe)

Garage-Double bay, gable front aluminum siding, overhead doors (c.1930-50) (14' x 12').

STATEMENT OF SIGNIFICANCE:

This handsome, well-preserved, Dutch Colonial Revival house is the only example of such architecture on Staniford Road. It may have been built by its first occupant, Alfred Trombley. Its springs eaves facade contributes visual variety to the rectalinear streetscape.

REFERENCES:

Burlington Directory, 1926.

MAP: (Indicate North in Circle)



SURROUNDING ENVIRONMENT:

- Open Land ☐ Woodland ☐
- Scattered Buildings ☐
- Moderately Built Up ■
- Densely Built Up ☐
- Residential ■ Commercial ☐
- Agricultural ☐ Industrial ☐
- Roadside Strip Development ☐
- Other:

RECORDED BY:
KAREN CZAIKOWSKI

ORGANIZATION:
DIVISION FOR HISTORIC PRESERVATION

DATE RECORDED:
JUNE 1, 1983