

Legend

- Catch Basin
- Manhole


Gravity Main

- Combined Waste Water
- Sewage
- Storm Runoff
- Pressurized Main

E. coli sample taken from
N/E corner of Lake Forest Pond
@ 9:30 AM 8/2/2017

During time of sample, no evidence that
sanitary sewer flow had entered the pond.
Sample taken as a precautionary measure.

Flynn Ave
Sewage Force Main Break
8/1/2017
Incident Map



BURLINGTON
PUBLIC WORKS
WATER RESOURCES

234 Penny Lane
Burlington, VT 05401
(802) 863-4501



DRAWN
GJ
CHECKED

SCALE
1 in = 100 ft
DATE
8/2/2017